TASCAM GB-10

Corrections on the Owner's Manual

Specifications of "GUITAR IN jack" on page 95 in the Owner's Manual contain errors.

INCORRECT:

Minimum input level: +3 dBV (1.4 V), (INPUT volume at 7) Maximum input level: -25 dBV (0.05 V), (INPUT volume at 10)

CORRECT:

Maximum input level: +3 dBV (1.4 V), (INPUT volume at 7) Minimum input level: -25 dBV (0.05 V), (INPUT volume at 10)

D01136300A Printed in China